



MARINE AVIATION 2015 Aviation Combat Element Transition Strategy

MWSG OAG Brief 15 Feb 2006

Pre-Decisional For Official Use Only (FOUO) APP/APP-3 09/13/16



Purpose

Update brief on Marine Aviation 2015 ACE Transition Strategy

Format

- → Outline HQMC ACE Transition Strategy Analysis
- → Outline Year-by-Year phased Transition Strategy Recommendations



Background

- HQMC(A) has been developing
 Transition Strategy over past 18
 months, factors impacting
 Strategy Analysis included:
 - → Marine Aviation Plan (AVPLAN) Transitions
 - Stress on the Force WRT GWOT
 - Marine Aviation Readiness
 - Marine ACE T/O Reviews
 - → Marine Aviation Manning Levels
 - Marine Aviation Mishap Rate
 - ◆ ACE composition WRT MEU/MEB/ MEF
 - → TACAIR / Assault Support Balance
 - → Active / Reserve Component Balance

- 2015 ACE Transition Strategy briefs to-date:
 - →CMC / ACMC Mid Jun 05
 - **→**EOS 26 Jun 05
 - →Marine Air Board 11 Aug 05
 - →MROC 13 Sept 05
 - **→**EOS 18 Sept 05
 - →WG Conf 12 Oct 05
 - →Marine Air Board 13 Oct 05
 - ◆Transition Strategy WG Nov 05
 - MARFOR CGs Briefed Jan 06
 - MROC Feb 06
 - CMC Decision
 - Decision Brief on 7 Mar 06

2015 ACE Transition Strategy Analysis

Future Capabilities 🔲 Readiness

- **→21**st Century Marine Corps
- → Marine Aviation Plan (AVPLAN)
- → Training (Simulation)
 Transformation
- Heavy Lift Replacement (HLR)
 Requirement
- Assault Support Capabilities & MAGTF Fires Analysis (not yet completed)
- **→**QDR- Potential Impacts
- **→** BRAC

- Operational Tasking
- Unit Turn Around Ratios (TAR)
- Aircraft Inventory Management
- Unit / Aircrew Training and Readiness
- Aviation Training System (ATS)

Operational Safety

- 🔷 Mishap Rate
- CMC Directive
- **→** Aviation T/O Reviews

Fiscal

- → HLR / MV-22
- **→** MILCON



Future Capabilities Summary

- 2015 Marine Corps Force Planning requirements and decisions likely to require Marine Aviation capability and capacity force structure adjustments
- DoD TACAIR capacity will most likely be reduced during QDR
- DoN Maritime and Assault Support Lift aircraft mix decisions will potentially lead to MV-22 / HLR unit force structure changes
- Marine Aviation is executing T/M/S transitions now! Near-Term decisions are required to posture Total Force Lay down and MILCON requirements
- Training Transformation fundamentally changes Marine Aviation's approach to training, simulation training devices required across AC/RC
- Marine Aviation Heavy Lift Replacement (HLR) Aircraft is required for

T/M/S Transitions, AC / RC Force Lay Down, Future Training implications and TACAIR / Assault Support balance will impact Marine Aviation Functions and Force Structure



Readiness

Operational Tasking



Aircraft Inventory Management

Unit / Aircrew Training and Readiness



Readiness -- Unit Turn-around Ratios

3 Year Turn-around Ratios 1,2 (TAR) Jan 05- Dec 07

```
Future (FY-12)
Current
          1: 1.0 No Change (LA / HMH(E) UDP Gapped
VMU
          1: 1.9 No Change Except for 31st MEU Det
HMM
          1:1.25
HMLA
                       1.63
                       No Change
HMH (D) 1:1.7
VMAQ
          1: 2.0 No Change
HMH (E) 1:1.68
                       2.13
VMFA(AW) 1:2.32
                       1.76
VMFA
          1:2.45
                       1.95
VMA
          1:2.71
                       No Change
VMGR
          1:3.0 No Change
```

OP/Decisonal- For Official Use Only (FOUO) UNCLASSIFIED

Note 1: TAR = ratio of months deployed to months not deployed. Does not account for inter-deployment training impacts on PERSTEMPO

Note 2: Total force data, Data reflects actual deployment plans and use of

Assault Support Community TAR will continue to stress
Operating Force
Rebalance toward Irregular Warfare




Readiness -- Aviation Iraining

System

Current Marine Aviation Training Shortfalls

- Multiple Commands with shared Training Ownership
 - → TECOM / MAW / MCI
- Flight Lead and Instrument & NATOPS checks
 - → Stan/Eval not standardized across T/M/S's
- Simulation Training Devices Configuration
 - ♦ Not current in most Legacy aircraft
 - Training Gaps due to resource shortfalls
 - → Ranges, Ordnance, Aircraft / Simulator Availability



Aviation Training System addresses entire Training Continuum

- TECOM Single Training Manager
- Systems Approach to Training (SAT) Curriculum Development
- ◆ Electronic Training Management System
- Flight Leadership Standardization / Evaluation
- ◆ Instrument / NATOPS Standardization / Evaluation
- Concurrency Management System
- Simulator Certification Program
- Crew Resource Management Enhancements

Standardize, properly manned and funded Training

System



Readiness Summary

- Current and projected Operational Tasking will increase stress on AC TAR's as RC squadrons are demobilized
- Current Aircraft Inventory Shortfalls along with high GWOT utilization rates and numerous aircraft in Depot or MOD Maintenance cycles will have significant impact on CONUS unit training. HMLA, HMH and VMFA(AW) communities are impacted the most.
- Current Aviation Training System deficiencies do not support the end to end training continuum required for the aircraft

C HMH / HMLA Force Structure and VMFA(AW) Aircraft shortfalls
CAN NOT support Long Term Operational Tasking

larine Aviation must commit the Manpower and Fiscal Resource to address current Training and Standardization Deficiencies



Operational Satety - Misnap

Rate

10 Year Aviation Safety: FY 96 - FY 05

Total Class A Mishaps 115

Aircraft Destroyed 110

• Fatalities 196

- Supervisory Error 63%
- Average Mishap Rate 3.18

FY-05 Aviation Safety

- Class A Flight Mishaps
- Aircraft Destroyed 7
- Fatalities 33 /1







FY07-09 Operational Safety and Maint - O/I

Marine Aviation Maintenance - The Last 20 Years

VMA x 7 13 Less E5-E7 & 4 Less E3-E4! 7 Less E5-E7 & 1 Less E3-VMFA x 8

L3 Less E5-E7& 5 More E3-E4!

VMFA(AW) x 6

4 Less E5-E7 & 5 More

E3-E4

VMAO x 4 5 Less E5-E7 & 8 More

HMM/VMM x 14

E3-E4! VMGK X 3

26 Less E5-E8 & 12 More E3-E4

 $HMH(E) \times 6$ 18 Less E5-E7 & 10 More E3-E4! HML/A x 6 20 Less E5-E7 & 31 More E3-E4!

 $HMH(D) \times 3$ 18 Less E5-E7 & 9 Less E3-

- Reduced experience levels (supervision/ leadership) through negative grade shaping
- **Operational Commanders' dilemma**
 - Compromise NAMP/ 4790 and other directive compliance concerning QA/ MC or have reduced grade shape in critical maintenance work centers

O & I-Level Reviews: 11-14 Apr/26-28 July

- Horizontal cross-community analysis of AC and RC operational flying squadrons/MALS
- Standardized enlisted leadership/oversight requirements for Core Squadrons and **Detachments**
 - MC/QA, Maintenance Divisions, HQ/S-Shop Functions...

FY05 MARFOR Maintenance Inspection Results

O-level, 12% Off Track and 17% Need More Attention I-Level, 9% Off Track and 20% Need More Attention

Top 10 Maintenance programs graded as OFF-TRACK

- → Technical Directives
- **♦** SE Planned Maintenance System
- → Aircraft Maintenance Material Readiness List (AMMRL)
- **→** Central Technical Publications Library
- Quality Assurance
- Corrosion Prevention & Control
- → Tire & Wheel Maintenance Safety
- Tool Control
- NOMMP AWCAP Program
- ◆ HAZMAT

TRANSITION STRATEGY	TOTAL									
REQUIREMENTS	Α	ıC	Α	ıR	SM	ICR				
	MO	ME	MO	ME	MO	ME				
FIX AVIATION (AC/RC)										
O-LEVEL SAFETY (MC/QA/NATOPS)	0	(138)	0	(5)	0	(12)				
O-LEVEL MAINT (MECH-AF/AC/SEAT/ORD)	0	(129)	0	0	0	(40)				
MAG SAFETY (DSS/GSO/HAZMAT)	(10)	(10)	0	0	0	0				
I LEVEL SAFETY (MALS QA)	0	(6)	0	0	0	0				
REIN MAG-41	0	0	0	(9)	(8)	(25)				
REIN MALS-41	0	0	0	(8)	(4)	(97)				
REIN MAG-49	0	0	0	(9)	(8)	(25)				
REIN MALS-49	0	0	0	(8)	(4)	(97)				
TOTAL FY07-09 "FIX ACE T/O'S"	(10)	(283)	0	(39)	(24)	(296)				

FY07-09 Bottom Line from TO reviews Total Structure Requirement: (AC) 10 MO and 283 ME; (RC) 24 MO and 335 ME Total Grade Shape Requirement: 192 SNCO and 83 E5 and below



FY07-09 ACE Warfighting HQ T/Os

Current ACE HOs and TACC

- MAW & MAG HQ T/O Structure does not completely support Combat **Operations Requirements**
- Current X-billets across ACE HO T/Os result in manpower 'draft' from MAWs / MAGs / SQDNs and Individual Augments
- MTACS T/O does not reflect the TACC requirement (Total: 11 MO and 21 ME)

Draft TACC T/O

	Dialt IACC 1/0												
	RQMT OFF/EN L	T/O MAP OFF/ENL	AR	<u>SMCR</u> ←	C-BILLETS								
CURRENT OPS	47/45	15/12			AN 148/33								
LNO / AIRBOSS	47/17	1/4		atr.	39/13								
ALOC	10/13	10/12		, al . Y	0/0								
FUTURE OPS	61/22	20/12		indiled	33/9								
FUSION	14/0	2/0		orks etal	10/0								
FUTURE PLANS	6/8	1/8		Man o	5/0								
ACI	15/61	9/25			6/36								
TOTALS (ACE T/O Review)	200/166	58/73 (36%)	0/0 (0%)	0/0 (0%)	142/93 (64%)								
(ACL I/O REVIEW)		(30%)	1	1	1								
TOTALS (Avn Trans Strategy)	200/166	58/73 (36%)	2/12 (4%)	80/81 (44%)	60/0 (16%)								

Warfighting HQs Reviews 2-6 May/26-28 Jul 05

- Horizontal Cross-HQ analysis conducted by MARFORs, MAWs, and **HOMC AVN**
- Draft MAW TACC T/O Developed from 3rd MAW OIF Lessons Learned

Status

- **Draft MAW TACC T/O 84% resourced**
 - SMCR 4th MAW TACC Dets "Warm start" for AC MAWs
 - C-Billet Reduction will minimize future IA requirements

Bottom Line

HO T/O Structure Shortfall: (AC) 80 MO / 146 ME; (AR) 5 MO / 6 ME; SMCR 24 MO / 123 ME

FY07-09 "Fix ACE T/O" Init Provides: (AC) 10 MO / 10 ME; (AR) 17 ME; (SMCR) 12 MO / **122 ME**



Bottom Line
ATS Structure Requirement (AC) 87 MO / 34 ME / 10 Civ



Manpower Summary FY07-09

COMPENSATION SOURCE	TOTAL						TRANSITION STRATEGY	age			AL		
COMPENSATION SOURCE		AC	А	ıR	SI	MCR	REQUIREMENTS		AC	A			ICR
	MO	ME	MO	ME	MO	ME		MO	ME	MO	ME	MO	ME
DEACTIVATE VMFA(AW)332	43	226	0	0	0	0	CAPABILITY REALIGNMENT						
DEACTIVATE VMFA-134	5	91	1	27	20	79	ACTIVATE/REALIGN TO AC HMH-XXX(769)	(41)	(296)	0	0	0	0
DEACTIVATE VMFA-212	24	219	0	0	0	0	REALIGN HMH-772 AS HMH-772(-)	(3)	(76)	(5)	(20)	(14)	(42)
DEACTIVATE VMFA-142 (112 T/O: 8830D)	5	88	1	28	20	79	ACTIVATE/REALIGN TO AC HMLA-XXX(773)	(70)	(387)	0	0	0	0
DEACTIVATE MAG-42	4	14	1	7	18	65	REALIGN HMLA-775(-) CP to MG (8970A)	(4)	(90)	(5)	(31)	(39)	(146)
DEACTIVATE MALS-42	4	18	2	13	18	239	REALIGN RC HMLA-775(A) FR JT/BC	(4)	(72)	(3)	(13)	(13)	(37)
DEACTIVATE/REALIGN TO AC HMH-769	2	88	5	14	17	40	4MAW OSA MISSION SUPPORT	0	0	(9)	(7)	(25)	0
REALIGN HMH-772 AS HMH-772(-)	3	87	4	12	17	42	FIX AVIATION (AC/RC)		(400)	-	(=)	-	(40)
REALIGN HMLA-773(9AC)	3	60	4	23	13	39	O-LEVEL SAFETY (MC/QA/NATOPS)	0	(138)	0	(5) O	0	(12)
REALIGN HMLA-773(18AC)	5	89	5	30	39	147	O-LEVEL MAINT (MECH-AF/AC/SEAT/ORD)	0	(129)	0	(1)	0	(21)
REALIGN HMLA-775 (-) CP/MG	4	90	5	31	39	146	O-LEVEL LOG (EMBARK/SUPPLY)	0 (10)	(36) (10)	0	(<u>1)</u>	0	(17) 0
REALIGN HMLA-775(A) FR JT/BC	5	72	2	13	13	37			(6)	0	0	0	0
DEACTIVATE MAG-46	4	14	n	8	18	66	I LEVEL SAFETY (MALS QA) O LEVEL INTEL (CLERKS)		(0)	0	(1)	0	(3)
4MAW OSA MISSION SUPPORT	9	0	0	0	0	0	4MAW HQ TACC WEST		0	(2)	(8)	(90)	(38)
MARFOR TACC IMA DETS	0	0	0	0	76	4	4MAW HQ TACC WEST		0	(2)	(8)	(90)	(38)
AC MALS CAS REALIGNMENT	0	34	n	n	n	0	4MAW HQ STAFF AC MIRROR		0	(7)	(8)	(32)	(130)
VFA-106/H-1 UPGRADES REALIGNMENT	2	38	0	0	0	0	4MAW HQ STAFF AC MIRROR REIN MAG-41		0	0	(9)	(4)	(25)
CNATRA REALIGNMENT	15	0	n	0	0	0	REIN MALS-41	0	0	0	(8)	(1)	(56)
HMM (T) -164 T/O ADJUSTMENT	0	43	0	0	0	0	REIN MAG-49	n	0	0	(9)	(4)	(25)
HLR STRUCTURE REALIGNMENT	0	12	n	n	0	0	REIN MALS-49	n	0	0	(8)	(1)	(56)
MWSS GIVE BACK	2	1	0	0	0	0	AVIATION TRAINING SYSTEMS	Ü	Ū	Ü	(0)	(1)	(30)
COA COMP/TRADE SPACE			J	- J	Ū	Ü	ATS STAN/EVAL	(1)	(4)	0	0	0	0
SITE SUPPORT CAMP PEN (8999C)	1	3	1	6	1	0	ATS CORE	(6)	(1)	0	0	0	0
SITE SUPPORT JOHNSTOWN (8999F)	2	2	1	2	0	0	4MAW ATS STAN/EVAL	0	0	(3)	(3)	0	0
SITE SUPPORT MARIETTA (8899B)	0	1	1	0	2	0	4MAW ATS CORE	0	0	(3)	(3)	0	0
SITE SUPPORT MIRAMAR (8999A)	2	3	2	1	2	1	MISC						
FDR (404 MECHS) FT WORTH (8810T)	0	7	0	0	0	0	JSF/OTHER DT	0	(14)	0	0	0	0
FDR (404 MECHS) BEAUFORT (8810Q)	0	4	0	0	0	0	JSF/HLR/OTHER OT	0	(37)	0	0	0	0
AR STRUCTURE BUY-BACK (FSPG 99)	0	0	5	7	0	0	JSF JITC (EGLIN AFB)	0	(25)	0	0	0	0
AR STRUCTURE BUY-BACK (AR ME TO AC ME)	0	 80	n	-80	0	0	HMLA FRS UPGRADE DIFF TRAINING		0	0	0	0	0
RC VMFA TRADE SPACE (8830A)	1	0	-1	0	0	0	HMLA FRS - ADDITIONAL SQDN	(3)	(73)	0	0	0	0
FW MALS CORE SUPPLY RIGHT-SIZING (8810)	0	15	0	0	0	0	HMH FRS - ADDITIONAL SQDN	(3)	(20)	0	0	0	0
FW MALS CORE ORD (6541) RIGHT-SIZING (8810)	0	10	0	0	0	0	FY REQUIREMENT TOTAL	(145)	(1414)	(39)	(142)	(313)	(646)
RW MALS SUPPLY REDUCTION (8910)	0	5	0	0	0	0	FY BALANCE / SUB-TOTAL	0	0	0	0	0	338
FY COMPENSATION TOTAL	145	1414	39	142	313	984	FY CUMULATIVE TOTAL						

Total Structure Requirement: (AC) 145 MO/1414 ME; (RC) 352 MO/788 ME Total Grade Shape Requirement: 42 MO and 364 ME



Fiscal - HLR / MV-22

TY\$M	FY07	FY08	FY09	FY10	FY11	FY07-11
HLR PB-06 Baseline	300.1	341.0	351.4	369.7	363.9	1726.1
HLR AIR4.2 Cost Estimate	361.0	461.0	618.0	602.0	551.0	2593.0
HLR Shortfall	(60.9)	(120.0)	(266.6)	(232.3)	(187.1)	(866.9)
MV-22 Log Support Shortfall					(170.0)	(170.0)

- HLR funding required to enter Milestone B
- V-22 funding required to enable Multi-Year Procurement Contract

THE CONTRACTOR OF THE PARTY OF

Summary

Summary

Future Capabilities

- →Increase AC Assault Support Capacity / Capability
- →Increased Manpower Requirements during AVPLAN Transitions

Readiness

- Rebalance of AC / RC Assault Support Capacity warranted by Operational Tasking, TAR and Aircraft Inventory Shortfalls
- → Reduction of VMFA(AW) capacity warranted due to F/A-18D aircraft inventory shortfall
- → Fully Functional and Resourced ATS required to execute Aviation Training
 Transformation

Operational Safety

→ ACE T/O adjustments are warranted to address ORM, Warfighting Capability and Transition manpower MARFOR / HQMC identified shortfalls

Fiscal

→ HLR and MV-22 have PR-07 funding shortfalls approaching upcoming Acquisition Milestones and Multi-Year Procurement contract



Transition Strategy Execution Considerations


- ACE Transition Strategy would required an executable year by year phased approach from FY-07 to FY-15
 - Manpower TOCR / Troop List Timing
 - Unit Activations and Deactivations and impacts on Deployment Rotations
 - → Sequenced East / West Coast MILCON Plan Strategy
- Activation of one AC HMH / HMLA from RC Structure
 - ◆Addresses HMH / HMLA TAR and Force Structure Shortfalls
- Relocation of RC Squadrons to AC bases
 - →Addresses Marine Aviation Training System Strategy
 - Reduces MALS duplication of effort
- Marine Corps acceptance of near term decrease in TACAIR Capacity / Sortie Generation until JSF FOC
 - ◆Addresses FA-18D Aircraft Inventory Shortfall
 - →Addresses Manpower required to fully resource adjusted Aviation T/O's
- Marine Corps acceptance of decreased RC MAG HQ's
 - Addresses Manpower required to fully resource adjusted Aviation T/O's to insure relevant Warfighting structure in remaining MAW / MAG HQ and TACC

Transition Strategy driven by Manpower Requirements for AC HMH/HMLA Standup, Fix Aviation T/Os and ATS

Standup



Aviation Combat Element 2005



18



2007 Execution

- Deactivate 1 x AC FA-18D sqdn
- Deactivate 1 x RC FA-18A+ sqdn
- Establish 4th MAW TACC Dets
- O/I-Level Safety and Maintenance Fixes

	FY07						TRANSITION STRATEGY		FY07						
							REQUIREMENTS	AC		AR		SMCR			
COMPENSATION SOURCE						·	MO	ME	MO	ME	MO	ME			
	A	C C	AR		SMCR		CAPABILITY REALIGNMENT								
	MO	ME	MO			ME	4MAW OSA MISSION SUPPORT				(7)				
	MU	IYIE	MU	IYIE	MO	IYIE	FIX AVIATION (AC/RC)								
DEACTIVATE UMEA/AIAI\OOO	40	226					O-LEVEL SAFETY (MC/QA/NATOPS)		(138)		(5)	_	(12)		
DEACTIVATE VMFA(AW)332	43	220					O-LEVEL MAINT (MECH-AF/AC/SEAT/ORD)		(129)				(21)		
DEACTIVATE VMFA-142	5	91	1	27 20 79		79	O-LEVEL LOG (EMBARK/SUPPLY)		(36)		(1)		(17)		
DEACTIVATE VINIFA-142	,	71		21	21 20 19		MAG SAFETY (DSS/GSO/HAZMAT)	(10)	(10)						
MARFOR TACC IMA DETS				76 4		4	I LEVEL SAFETY (MALS QA)		(6)						
							O LEVEL INTEL (CLERKS)				(1)		(3)		
AC MALS CAS REALIGNMENT		34					4MAW HQ TACC WEST			(1)		(40)	(2)		
VFA-106/H-1 UPGRADES REALIGNMENT	2	17					4MAW HQ TACC EAST			(1)		(40)	(2)		
ALA-TOO/U-T OLGKADES KEARTGIAINENT		17					AVIATION TRAINING SYSTEMS ATS STAN/EVAL		(4)						
HLR STRUCTURE REALIGNMENT		12					ATS CORE	(6)	(4)						
AAA AAMBADADE ODAAC							MISC	(0)							
COA COMP/TRADE SPACE							JSF/OTHER DT		(14)						
FDR (404 MECHS) FT WORTH (8810T)		7					HMLA FRS UPGRADE DIFF TRAINING		0						
LDK (404 MECH2) ET MOK IH (99101)		- /					HMLA FRS - ADDITIONAL SODN	(3)	(30)						
AR STRUCTURE BUY-BACK (FSPG 99)			1	2			HMH FRS - ADDITIONAL SQDN	(3)	(20)						
,							FY REQUIREMENT TOTAL	(22)	(387)	(2)	(14)	(80)	(57)		
FY COMPENSATION TOTAL	50	387	2	29	96	83	FY BALANCE / SUB-TOTAL	28	0	0	15	16	26		



2008 Execution

- Deactivate 1 x AC FA-18C Sqdn
- Deactivate 1 x RC FA-18A+ Sqdn
- Deactivate MAG-42 HQ/ MALS-42
- Relocate 1 x AC FA-18D Sqdn to Iwakuni
- Relocate VMX-22 to NAS Pax River
- Transition 1 x RC HMH (769) to 1 x AC HMH-(XXX) and relocate from Edwards to MCAS Cherry Point/New River
- Realign 1 x RC HMH (772) to 1 x RC HMH(-)
 - Relocate to McGuire according to BRAC

Reinforce MAG/MALS-41/49

Reillioice MAG/MALS-41/49													
			FY	'08			TRANSITION STRATEGY	FY08					
COMPENSATION SOURCE							REQUIREMENTS	AC		AR		SMCR	
	A	VC O	A	ıR	SMCR			MO	ME	MO	ME	MO	ME
	MO	ME	MO	ME	MO	ME	CAPABILITY REALIGNMENT						
DEACTIVATE VMFA-212	24	219					ACTIVATE/REALIGN TO AC HMH-XXX(769)	(41)	(296)				
	5	88	1	28	20	79	REALIGN HMH-772 AS HMH-772(-)	(3)	(76)	(5)	(20)	(14)	(42)
DEACTIVATE VMFA-134				20			FIX AVIATION (AC/RC)						
DEACTIVATE MAG-42	4	14	1	7	18	65	4MAW HQ TACC WEST			(1)	(8)	(32)	(36)
DEACTIVATE MALS-42	4	18	2	13	18	239	4MAW HQ TACC EAST			(1)	(8)	(32)	(36)
DEACTIVATE/REALIGN TO AC HMH-769	2	88	5	14	17	40	4MAW HQ STAFF AC MIRROR			(7)	(8)	(18)	(107)
REALIGN HMH-772 AS HMH-772(-)	3	87	4	12	17	42	REIN MAG-41				(9)	(4)	(25)
· · · · · · · · · · · · · · · · · · ·			•			- '-	REIN MALS-41				(8)	(1)	(56)
VFA-106/H-1 UPGRADES REALIGNMENT		10					REIN MAG-49				(9)	(4)	(25)
MWSS GIVE BACK	2	1					REIN MALS-49				(8)	(1)	(56)
COA COMP/TRADE SPACE							AVIATION TRAINING SYSTEMS						
EDD (404 MECUC) DEAUEODT (D0100)							ATS CORE		(1)				
FDR (404 MECHS) BEAUFORT (8810Q)		2					HMLA FRS - ADDITIONAL SQDN		(43)				
AR STRUCTURE BUY-BACK (FSPG 99)			2	2			FY REQUIREMENT TOTAL	(44)	(416)	(14)	(78)	(106)	(383)
RC VMFA TRADE SPACE (8830A)	1		-1				FY BALANCE / SUB-TOTAL	1	111	0	(2)	(16)	82
FY COMPENSATION TOTAL	45	527	14	76	90	465	FY CUMULATIVE TOTAL	29	111	0	13	0	108

20



2009 Execution

- Deactivate MAG-46 HQ
- Relocate AC HMM-268 from Camp Pendleton to Miramar
- Deactivate RC HMLA-773 (-) and Det A & Establish AC HMLA-XXX
- Relocate RC HMLA-775A from Johnstown to McGuire, Reinforce, and Redesignate HMLA-775(-)
- Establish HMLA-775A at Belle Chasse
- Realign HMLA-775 (-) & HMLA-775A under MAG-49
- Realign RC VMGR-452 under MAG-41
- Realign RC HMM-764 under MAG-41

IMA Dets ISO OSA CONUS/K-Bay


II-IA DCLS ISO OSA CONOS/IX DUY													
COMPENSATION SOURCE	FY09						TRANSITION STRATEGY	FY09					
COMPENSATION SOURCE	Α	AC	А	ıR	SI	MCR	REQUIREMENTS	AC		AR		SMCR	
	MO	ME	MO	ME	MO	ME		MO	ME	MO	ME	MO	ME
REALIGN HMLA-773(9AC)	3	60	4	23	13	39	CAPABILITY REALIGNMENT						
REALIGN HMLA-773(18AC)	5	89	5	30	39	147	ACTIVATE/REALIGN TO AC HMLA-XXX(773)	(70)	(387)				
REALIGN HMLA-775 (-) CP/MG	4	90	5	31	39	146	REALIGN HMLA-775(-) CP to MG (8970A)	(4)	(90)	(5)	(31)	(39)	(146)
REALIGN HMLA-775(A) FR JT/BC	5	72	2	13	13	37	REALIGN RC HMLA-775(A) FR JT/BC	(4)	(72)	(3)	(13)	(13)	(37)
DEACTIVATE MAG-46	4	14		8	18	66	4MAW OSA MISSION SUPPORT		\ <i>y</i>	(9)	(/	(25)	(/
4MAW OSA MISSION SUPPORT	9						FIX AVIATION (AC/RC)			(-)		(25)	
VFA-106/H-1 UPGRADES REALIGNMENT		11					4MAW HQ TACC WEST					(18)	
CNATRA REALIGNMENT	15						4MAW HQ TACC EAST					(18)	
HMM (T) -164 T/O ADJUSTMENT		43					4MAW HQ STAFF AC MIRROR					(14)	(23)
COA COMP/TRADE SPACE							-					(14)	(23)
SITE SUPPORT CAMP PEN (8999C)	1	3	1	6	1		AVIATION TRAINING SYSTEMS ATS STAN/EVAL	4.1					
SITE SUPPORT JOHNSTOWN (8999F)	2	2	1	2			·	(1)					
SITE SUPPORT MARIETTA (8899B)		1	1		2		4MAW ATS STAN/EVAL			(3)	(3)		
SITE SUPPORT MIRAMAR (8999A)	2	3	2	1	2	1	4MAW ATS CORE			(3)	(3)		
FDR (404 MECHS) BEAUFORT (8810Q)		2					MISC						
AR STRUCTURE BUY-BACK (FSPG 99)			2	3			JSF/HLR/OTHER OT		(37)				
AR STRUCTURE BUY-BACK (AR ME TO AC ME)		80		-80			JSF JITC (EGLIN AFB)		(25)				
FW MALS CORE SUPPLY RIGHT-SIZING (8810)		15					FY REQUIREMENT TOTAL	(79)	(611)	(23)	(50)	(127)	(206)
FW MALS CORE ORD (6541) RIGHT-SIZING (8810)		10					The state of the s					()	
RW MALS SUPPLY REDUCTION (8910)		5					FY BALANCE / SUB-TOTAL	(29)	(111)	0	(13)	0	230
FY COMPENSATION TOTAL	50	500	23	37	127	436	FY CUMULATIVE TOTAL	0	0	0	0	0	338

OPe/Deciso/hal-- For Official Use Only (FOUO) UNCLASSIFIFD

21



Aviation Combat Element 2009





STRATEGY

FY07

- -Deactivate 1 x AC FA-18D sqdn (sqdn TBD)
- -Deactivate 1 x RC FA-18A+ sqdn (sqdn TBD)

FY08

- -Deactivate 1 x AC FA-18C sqdn (sqdn TBD)
- -Deactivate 1 x RC FA-18A+ sqdn (sqdn TBD)
- -Deactivate MAG-42 HO / MALS-42
- -Relocate AC FA-18D sqdn to Iwakuni (sqdn TBD)
- -Relocate VMX-22 to NAS Pax River
- -Deactivate 1 x RC HMH (769)
- -Reduce 1 RC HMH (772) to HMH(-)
- -Activate 1x AC HMH-(XXX) at Cherry Pt
- -Realign RC HMM-774 under MAG-49

FY09

- -Deactivate MAG-46 HQ
- -Deactivate RC HMLA-773
- -Activate AC HMLA-(XXX) at Cherry Pt
- -Relocate RC HMLA-775A Johnstown to McGuire and redesignate HMLA-775(-) with 12 AH / 6 UH
- -Relocate HMLA 775(-) CPCA to Bell Chase and redesignate HMLA-775A with 6 AH / 3 UH
- -Realign RC HMLA-775 under MAG-49
- -Realign RC HMM-764 under MAG-41
- -Realign VMFT-401 under MAG-41
- -Reinforce 4th MAW's MAG HQs (RC TACC dets)

FY10

- -Relocate 1 x FA-18D AC sqdn Beaufort to Cherry Pt*
- -Relocate HMT-302 New River to Miramar*

FY11

-Relocate 1 x FA-18D AC sqdn Beaufort to Cherry Pt*
-Relocate HMLA & HMH-(XXX) Cherry Pt to New

FY12

-Relocate 1 x FA-18C AC sqdn Beaufort to Cherry Pt* -Xstn(JSF)/ relocate 1 x FA-18C sqdn Miramar to Yuma*

FY13*

- -Deactivate MATSG-53 (EA6-B FRS)**
- -Deactivate 1 x VMAQ sqdn**
- -Reactivate RC HMM/VMM-769 under MAG-49 (Loc TBD)
- -Relocate 2 x FA-18C AC sqdn Beaufort to Cherry Pt
- -Xstn(ISF)/ relocate 2 x FA-18C Miramar to Yuma
- -Relocate AC HMM-268 Camp Pendleton to Miramar
- -Relocate AC HMM-364 Camp Pendleton to Miramar

FY14*

- -Activate 1 AC VMU, CPEN
- -Activate 1 RC VMU under MAG-41 Ft Worth
- -Deactivate 1 x VMAQ sqdn**
- -Relocate 1 x FA-18C AC sqdn Beaufort to Cherry Pt
- -Xstn(JSF)/ relocate 2 x FA-18D Miramar to Yuma

FY15*


- -Deactivate 2 x VMAQ sqdns**
- -Relocate RC HMM-764 Edwards to Miramar
- -Relocate RC HMM-774 Norfolk to Miramar

(U) Maintains six functions of Marine Aviation and all T/M/S in Reserve Force and addresses long standing manpower shortfalls

** (U) Based on DoD EW Roadmap



Aviation Combat Element 2015





2007-2015 Transition Strategy Summary

- TACAIR Force Structure
 - Deactivate 1 AC VMFA(AW), 1 AC VMFA, 2 RC VMFA, 4 VMAQ's,
- Assault Support Force Structure
 - → Deactivate 1 RC HMH, Reduce 1 RC HMH to HMH(-)
 - → Deactivate 1 RC HMLA
 - ◆Activate 1 AC HMH and 1 AC HMLA
 - → Reactivate 2 RC HMM/VMM (2012-2013)
- **VMU Force Structure**
 - ◆Activate 1 AC and 1 RC VMU
- Headquarters Force Structure
 - Deactivate 2 RC MAG HQ
- Training Force Structure

CMC Decision To Date: Approved FY07-08 Execution





Questions

09/13/16 **UNCLASSIFIED** 26



ROAD AHEAD

Near term (Winter)

- Brief MARFOR Commanders
- Brief MROC
- → Seek CMC approval for FY 09
- Continue integrating with COMMARFORPAC basing initiative
- Develop plan to implement Aviation Training System (TECOM / DC/AVN)
- Informal briefings to Congress

■Mid term (Spring)


- → After 15 April: Formal notification to Congress
- → Participate in USMC 2015 capabilities assessment
- → Prepare 5400 bulletin for FY-07
- → Participate in DoN JSF Joint Integrated Training Center discussions

Long term (Summer - forward)

- **→** DoD Airborne Electronic Attack planning ICW USMC AEA requirement
- DoN JSF Capabilities / Mix Study



FY07-09 Structure ISO AC ATS Endstate






Other Back Up Slides



FIGHTER ATTACK SURGE CAPACITY

FIGHTER ATTACK SURGE SORTIES




FISCAL YEAR

TRANSITION SQUADRONS ACCOUNTED FOR



FIGHTER ATTACK SUSTAIN CAPACITY

FIGHTER ATTACK **SUSTAIN SORTIES**





Readiness - PMAA Operational Tasking MAR

06

Projected Deployed Active Component Only 1 March 2006 GNFPP/GWOT/FDNF/UDP

Contingency Aircraft
Requirement

AC and RC

	GNFPP SQDNS /A/C	GWOT SQDNS / A/C	FDNF/31st MEU SQDNS / A/C	UDP SQDNS /A/C	Total SQDNS/A/ C	% Total AC PMAA	
HMM 144	2/24	1/12	2/24	0/0	5/60	42%	
HMH (E) 96	.25/4	1/16	.25/4	0/0	1.5/24	25%	
HMH (D) 30	0/0	1/10	0/0	0/0	1/10	33%	
HMLA 162	.25/6	1.75/48	.33/9	0/0	2.33/63	39%	
VMA 98	.5/6	1/10	.5/6	0/0	2/22	22%	
Note: Mar 06 8 95 .	1/10	0/0	1/12	1/12	3/34	38%	yak

SQDNS	A/C	% Total PMAA (Mar 06)
12	144	86%
4.25	68	61%
3	30	100%
4.75	126	58%
5.75	92	94%
7	84	71%

7 V 3 V 2

RC Assault Support demobilization will increase stress on AC Assault Support Community



2010 Operational Tasking - Strategy Implemented

Projected Deployed

Active Component Only

2006 tasking with March 2010 force
GNFPP/GWOT/FDNF/UDP

Contingency Aircraft
Requirement

AC and RC

		GNFPP SQDNS /A/C	GWOT SQDNS / A/C	FDNF/31st MEU SQDNS / A/C	UDP SQDNS /A/C	Total SQDNS/A/ C	% Total AC PMAA	
	нмм/VMM 144	2/24	1/12	2/24	0/0	5/60	42%	
	HMH (E) 112	.25/4	1/16	.25/4	0/0	1.5/24	21%	
	HMH (D) 30	0/0	1/10	0/0	0/0	1/10	33%	
	HMLA 189	.25/6	1.75/48	.33/9	0/0	2.33/63	33%	
	VMA 98	.5/6	1/10	.5/6	0/0	2/22	22%	
C	lote Mar 10 o ns plete IAW	1/10	0/0	1/12	1/12	3/34	43%	;H
9	1 _v (

% Total **PMAA SQDNS** A/C (Mar 06) 12 86% 144 4.25 68 **59%** 30 100% 4.75 58% 126 5.75 92 94% 92% 7 84

35% of AC force deployed at current day OPTEMPO and 74% of the total force is required for the most stressing MCO.